

Oil Field Environmental Incident Summary

Incident: 20150804162753 **Date/Time of Notice:** 08/04/2015 16:27

Responsible Party: HRC OPERATING, LLC

Well Operator: HRC OPERATING, LLC

Well Name: FORT BERTHOLD 148-94-9C-04-5H

Field Name: EAGLE NEST

Well File #: 22979

Date Incident: 8/4/2015 **Time Incident:** 05:00

Facility ID Number:

County: DUNN

Twp: 148

Rng: 94

Sec: 9

Qtr: SW SE

Location Description:

Submitted By: Julia Traster

Received By:

Contact Person: Chris Martinez
1801 CALIFORNIA STREET
SUITE 3500
DENVER, CO 80202

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building: 1 Mile

Distance Nearest Water Well: 1 Mile

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: Yes - On Constructed Well Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	2	Barrels	2	Barrels	2	barrels
Other						

Description of Other Released Contaminant:

Inspected:

Written Report Received: 1/19/2016

Clean Up Concluded: 8/4/2015

Risk Evaluation:

Low health hazard

Areal Extent:

Approximately 2000 square feet around and in the vicinity of the wellhead.

Potential Environmental Impacts:

Low risk of impact to surface or groundwater. Spill remained within well site boundaries.

Action Taken or Planned:

The needle valve at the wellhead was repaired/replaced. All free liquids were picked up with a vacuum truck and hauled to a disposal well. All wetted soil and scoria rock was over-excavated and will be hauled to R360 Prairie Disposal on August 5, 2015.

Wastes Disposal Location: All free liquids were picked up with a vacuum truck and hauled to a disposal well. All wetted soil and scoria rock was over-excavated and will be hauled to R360 Prairie Disposal on August 5, 2015.

Agencies Involved:**Updates**

Date: 8/4/2015 **Status:** Reviewed - Assigned to Other Agency

Author: Crowdus, Kory

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to valve/piping connection leak, remained on location according to the report. Location is within MHA nation. Report forwarded to MHA environmental, BIA, and EPA.